



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-1-14 Operator Merrion API #30-0 45-09256
Property Name Ruby Corcoran Well No. 1 Location: Unit Section 25 Township 30 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 251 Intermediate N/A Casing 218 Bradenhead 67

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>21</u>		<u>219</u>		
10 min	<u>16</u>		<u>219</u>		
15 min	<u>14</u>		<u>219</u>		
20 min	<u>12</u>		<u>220</u>		
25 min	<u>9</u>		<u>220</u>		
30 min	<u>10</u>		<u>220</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>/</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water	<u>/</u>	
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

RCUD OCT 1 '14
OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 42

INTERMEDIATE N/A

REMARKS:

Medium blow - Black water - at 2 min. - 3 gallons
in 30 seconds. Shut in blew gas when I pulled again
5-10-15-20-25-30 Water & Gas Samples taken

By Tim Merilatt
Contract Pumper
(Position)

Witness Monica Kuehling

E-mail address