



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III/3district.htm](http://emnr.d.state.nm.us/ocd/District%20III/3district.htm)

RCUD SEP 30 '11

OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 30 SEP 2011 Operator ENEAL EST API #30-0 4510088

Property Name PAXE Well No. 1 Location: Unit 1C Section 35 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate N/A Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min			30		
10 min			30		
15 min			30		
20 min				N/A	
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By Alex chao

Witness Sammy

pumper
(Position)

E-mail address _____