



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 20-OCT-2011 Operator EVERGREEN API #30-0 39-26214

Property Name EUL CANYON SWD Well No. 1 Location: Unit 4 Section 29 Township 32 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 400 Intermediate N/A Casing 290 Bradenhead 235

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			290		
10 min			290		
15 min			290		
20 min			290		
25 min			285		
30 min			280		

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

OIL CONS. DIV DIST. 3
OCT 20 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 23

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN TO

NOTHING IN 5 SECONDS. Casing FELL TO 280 PSI

WHILE WATER WAS BEING PUMPED DOWN THE TUBING

By

[Signature]
District Engineer
(Position)

Witness

[Signature]

E-mail address _____