



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/25/14 Operator Enervest API #30-0 45-31029

Property Name Arnstein Well No. 1B Location: Unit 1 Section 18 Township 9N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 90 Intermediate 60 Casing 90 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0	60	90	0	90
10 min	0	60	90	0	91
15 min	0	60	90	0	91
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	X
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

RCUD OCT 17 '14
OIL CONS. DIV.

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 10 INTERMEDIATE 0

REMARKS:

Braden puffs down in less than 1 second
Intermediate has steady blow down to nothing audible can
see vapors.

By Jamy Schmitt
Operator
(Position)

Witness _____

E-mail address _____