



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District IU3/district.htm](http://emmr.state.nm.us/ocd/District%20IU3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/26/2014 Operator Enharvest API #30-0 45-32691

Property Name Rio Bravo 27 Well No. 08 Location: Unit 2 Section 27 Township 31N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 260 Intermediate Casing 75 Bradenhead 20

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		75		
10 min	0		75		
15 min	0		75		
20 min	0		75		
25 min	0		75		
30 min	0		75		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	ROVD OCT 17 '14
Surges	OIL CONS. DIV.
Down to Nothing ☒	DIST. 3
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: 4 1/2" liner no intermediate.

By [Signature]
Pumper
(Position)

Witness

E-mail address