



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmrnd.state.nm.us/ocd/District III3district.htm](http://emmrnd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/26/2014 Operator Enervest API #30-0 45-3333 7

Property Name Big Lake 26 Well No. 55 Location: Unit 3 Section 26 Township 31N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 55 Intermediate Casing 55 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	RCVD OCT 17 '14
Surges	OIL CONS. DIV.
Down to Nothing	DIST. 3
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: 4 1/2" liner no intermediate.

By [Signature]

Witness

(Position)

E-mail address