

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran	RCUD OCT 14 '14
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	OIL CONS. DIV.
Facility Name: Hughes A1E	Facility Type: Natural Gas Well	DIST. 3

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004525459
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter: E	Section: 27	Township: T29N	Range: 08W	Feet from the: 1810	North/South Line: North	Feet from the: 1080	East/West Line: West	County: San Juan
-------------------	----------------	-------------------	---------------	------------------------	----------------------------	------------------------	-------------------------	------------------

Latitude 36.69908 Longitude 107.6691

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 262 MCF	Volume Recovered: None
Source of Release: Nipple on separator	Date and Hour of Occurrence: 10/5/14 6 am - 10/8/14 1 pm	Date and Hour of Discovery: 10/8/14
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Found gas leaking by 2 inch nipple from compressor discharge line to discharge scrubber on separator. Well is shut-in awaiting repairs.

Describe Area Affected and Cleanup Action Taken.*

Natural gas dissipated to atmosphere; no clean-up action possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 11/13/14	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/9/2014 Phone: 505-326-9457		

* Attach Additional Sheets If Necessary

#NCS 1431738825