

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Roddy Production Company	Contact: Jeremy Divine
Address: P O Box 2221, Farmington NM 87499	Telephone No. 432 557 6778
Facility Name: Chacon Jicarilla Apache D #009	Facility Type: Oil Well
Surface Owner: Jicarilla Apache Nation	Mineral Owner: Jicarilla Apache Nation
API No. 30-043-20430	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	23	23N	3W	790'	South	1850'	East	Sandoval

Latitude: 36 deg. 12' 15.29" Longitude: 107 deg. 07' 23.78"

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 158 bbls	Volume Recovered: 159.27bbls
Source of Release: 400 bbl Oil Tank	Date and Hour of Occurrence: 10-16-14 late evening	Date and Hour of Discovery: 12:00 pm 11-17-14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jason Sandoval w/ Jicarilla O&G found spill, spoke w/ Mr. Sandoval at 12:40 pm, Notified NMOCD at 2:55 pm	
By Whom? Jeremy Divine	Date and Hour: 10-17-14, 2:55 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

OIL CONS. DIV DIST. 3
OCT 21 2014

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On Thursday October 16 2014, lease operator drained water out of oil tank. When finished he mistakenly opened the valve all the way instead of closing and sealed the valve, draining 195.39 bbls out of oil tank, filling up fiberglass water tank w/ 37. 12 bbls and spilling 158.27 bbls onto the ground. Remediation will start in the next 2 to 5 days and will be completed according to Jicarilla Apache Oil & Gas Administration and NMOCD standards.

Describe Area Affected and Cleanup Action Taken.*

The area affected was the below grade tank and cellar it was placed in, approximately a 26' x 26' x 3' deep fenced area. Clean action taken: All of the oil was contained in the firewall on location. On 10-16-14 a vacuum truck picked up 148 bbls with a loss of 47 bbls. On 10-20-14 a steam cleaner was used to clean the soil and the inside/outside of the fiberglass tank. Another 11.27 bbls oil was recovered, total recovered 159.27 bbls. Clean up still in progress.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeremy Divine</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeremy Divine	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Foreman	Approval Date: 11/19/14	Expiration Date:
E-mail Address: jdivine@crowquest.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-20-14	Phone: 432 557 6778	

* Attach Additional Sheets If Necessary

#NCS 143 2335 728

①