



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-1-14 Operator Lizard Velazquez API #30-0 45-09055
Property Name Santiago de Cristo Well No. 1 Location: Unit 1 Section 34 Township 30 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate 1/4 Casing 0 Bradenhead 23

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg			
<u>Vapors</u> 5 min	<u>0</u>		<u>0</u>	Steady Flow	<u>/</u>	<u>Vapors</u>
<u>Vapors</u> 10 min	<u>0</u>		<u>0</u>	Surges		
<u>Vapors</u> 15 min	<u>0</u>		<u>0</u>	Down to Nothing		
20 min				Nothing		
25 min				Gas		
30 min				Gas & Water		
				Water		

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

DEC 01 2014

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE _____

REMARKS:

well has production packer, packer placed 40' at
well - left packer in & casing clear - need blow to
Vapors at 1 min 48 seconds.

By Edm Sullivan
Pumper
(Position)

Witness Monica Fuchling

E-mail address _____