



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emmrnd.state.nm.us/ocd/District/1034/index.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

MAY 10 2013

(submit 1 copy to above address)

Date of Test 5-8-13 Operator Chedron midcont API #30-0 39-06627

Property Name Rincon Well No. 91 Location: Unit 0 Section 11 Township 26 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 28 Intermediate X Casing 28 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Light Blow		28		
	Very light		28		
10 min	Very light		28		
15 min	Very light		28		
20 min	Very light		28		
25 min	Very light		28		
30 min	Very light		28		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS: Blowdown to Light Blow in 3 sec, then light blow for 1 min
then very light blow for rest of test

By Randy Calder
Calder service
(Position)

Witness _____

E-mail address Randy.C@calderservice.com

5-9-13