



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District/023/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

MAY 07 2013

Date of Test 4-29-13 Operator Calden mcdon API #30-039-06890

Property Name Rincon Well No. 139 Location: Unit 5 Section 25 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate X Casing 37 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME	Over		37		
5 min	Flow				
	Over		37		
10 min	Flow				
	Over		38		
15 min	Flow				
	Over		37		
20 min	Flow				
	Over		38		
25 min	Flow				
	Over		38		
30 min	Flow				

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>Very Light</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE X

REMARKS: Blew very light Blow for full Test

By Randy cal coté
calder service
(Position)

Witness _____

E-mail address Randy.c@calder service.com

4-20-1