



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.d.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

APR 23 2013

Date of Test 4-16-13 Operator Clevoon midcast API #30-039-06933

Property Name Rincon Well No 138 Location: Unit A Section 25 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 72 Intermediate X Casing 72 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME	<u>Close</u>				
5 min	<u>Blow</u>		<u>73</u>		
10 min	<u>Blow</u>		<u>74</u>		
15 min	<u>Blow</u>		<u>74</u>		
20 min	<u>Blow</u>		<u>75</u>		
25 min	<u>Blow</u>		<u>77</u>		
30 min	<u>Blow</u>		<u>77</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>X Light Blow</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE X

REMARKS:

Had Light Blow for Entire Test

By Randy Culcote

Witness _____

Culder service
(Position)

E-mail address Randy.c@calderservice.com

4-17-13