



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://omnrd.state.nm.us/focd/District/W3District.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 31 2013

Date of Test 5-9-13 Operator Chewon midwell API #30-0 39-27326

Property Name Rincon Well No. 136P Location: Unit F Section 23 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 70 Intermediate 115 Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	115	75	0	75
10 min	0	115	75	0	77
15 min	0	115	75	0	77
20 min	0	115	75	0	77
25 min	0	115	75	0	77
30 min	0	115	75	0	77

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Int Blew down to nothing in 6 sec, then dead

By Randy CalcoTE

Witness _____

Calder service

(Position)

E-mail address Randy.C@calder.service.com

R

5-16-13