



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-15-13 Operator Chevron Midcon API # 30-039-06975

Property Name Rincon Well No 137 Location: Unit 11 Section 24 Township 21 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 49 Intermediate 1 Casing 25 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	1	23	0	23
10 min	0	1	23	0	23
15 min	0	1	23	0	23
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>Light Blow 2mb X 40 sec</u>
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
APR 17 2013

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 1, 0

REMARKS:

By Randy Culcote

Witness _____

Culder Service
(Position)

E-mail address Randy.C@culderservice.com

4-16-13