



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.dnr.state.nm.us/oilconservation/district3/district3.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 10 2013

Date of Test 5-8-13 Operator Chelon incident API #30-0 39-25361

Property Name Rincon Well No. 187E Location: Unit 16 Section 35 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 49 Intermediate X Casing 55 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		55		
10 min	0		54		
15 min	0		54		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X 28sec
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS: Bradenhead Blew To 0 in 28sec

By Randy CalcoTE
Calder service
(Position)

Witness _____

E-mail address Randy.C@calderservice.com

5-9-13