



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://omnrd.state.nm.us/ocd/District11/District11.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 07 2013

Date of Test 5-2-13 Operator Chervon midwest API # 30-039-26997

Property Name Rincon Well No. 183R Location: Unit 4 Section 31 Township 27 Range 6

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 45 Intermediate 1 Casing 47 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	1	47	0	48	
10 min	0	1	48	0	47	
15 min	0	1	47	1	47	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	<u>X RFF</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By Randy Calder
calder service
(Position)

Witness _____

E-mail address Randy.C@calder service .com

5-3-13