



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-12-2015 Operator Enewest API #30-0 45-32187
Property Name Tajoya Well No. 1C Location: Unit Section 35 Township 32 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 79 Intermediate NA Casing 78 Bradenhead 122

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead		Csg	Int	Csg
	BH	Int			
TIME					
5 min	<u>20</u>		<u>80</u>		
10 min	<u>10</u>		<u>80</u>		
15 min	<u>6</u>		<u>82</u>		
20 min	<u>5</u>		<u>80</u>		
25 min	<u>4</u>		<u>80</u>		
30 min	<u>3</u>		<u>80</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u> </u>	<u> </u>
Surges	<u> </u>	<u> </u>
Down to Nothing	<u> </u>	<u> </u>
Nothing	<u> </u>	<u> </u>
Gas	<u> </u>	<u> </u>
Gas & Water	<u> </u>	<u> </u>
Water	<u> </u>	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 25 INTERMEDIATE NA

REMARKS: H₂S Remover (8722) trade name Spinguto Casing
Med blow to Vapor at 10 seconds to gurgling water at 20 sec.
Spitting t 8 min. Shut in to get pressure water never came back.

By [Signature]
Pumper
(Position)

Witness [Signature]
Wellbore Schematic
Gas samples were taken

E-mail address