



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-12-2015 Operator Enerwest API #30-0 45-32632
Property Name Tafuya 35 Well No. 5 Location: Unit Section 35 Township 32 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 121 Intermediate N/A Casing 120 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	11		102		
10 min	0		100		
15 min	0		99		
20 min	0		95		
25 min	0		95		
30 min	0		100		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

OIL CONS. DIV. DIST. 3
JAN 12 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Medium blow - dead at 10 min - well
Started flowing at 10 min.
Sug Samples taken

By Ry Ln
P. M. P.
(Position)

Witness Monica Kuehling
Wellbore schematic

E-mail address