



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-12-2015 Operator Emwest API #30-0 45-32689

Property Name Valance 33 Well No. 2 Location: Unit Section 33 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 102 Intermediate 114 Casing 48 Bradenhead 70

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		48		
10 min	0		48		
15 min	0		48		
20 min	0		48		
25 min	0		48		
30 min	0		48		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
JAN 12 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 4 INTERMEDIATE 114

REMARKS: Blew through 1/4 valve for just 50 seconds then
to 1" valve test of test. Light blow at 1 min 20 second
closed at 2 min 50 seconds.

By Rg for
Pumper
(Position)

Witness Mona Cechling
Gas samples taken.
need wellbore schematic

E-mail address