



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/1/05 Operator CHEVRON API #30-0 4523059
Property Name HANLEY A Well No. 1 Location: Unit 18 Section 29 Township 10 Range 10
Well Status (Shut-In or Producing) Tubing 213 Intermediate 0 Casing 0 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
INITIAL TEST 11:15


PRESSURES:				BRADENHEAD FLOWED	INTERMEDIATE FLOWED
TIME	BRADENHEAD	INTERMEDIATE	CASING		
11:20 5 minutes	0		0	Steady Flow	
11:25 10 minutes	0		0	Surges	
11:30 15 minutes	0		0	Down to Nothing <u>3 MIN</u>	
20 minutes				Nothing	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

11:35 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS: 1/4" BLEED DOWN



By MIKE PREYER
MAINTENANCE PLANNER
(Position)

Witness NONE - DARYL IS GONE
TOLD TO CONT TESTING

E-mail address MLPRE@CHEVRON.COM