



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/2/05 Operator FOUR STAR CHEVRON API # 30-04523116
Property Name BM HOUCK Well No. 1 Location: Unit 13 Section 29 Township 11 Range 11
Well Status (Shut-In or Producing) Tubing 186 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
INITIAL TEST: 8:40

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
8:45	0		0	Steady Flow	
8:50	0		0	Surges	
8:55	0		0	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

9:00 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

1/4" BLEEPER



By MIKE DREYER Witness NONE - DARYL IS GONE
MALDRE@CHEVRON.COM MAINTENANCE TOLD TO CONT TESTING
(Position) PLANNER
E-mail address MALDRE@CHEVRONTEXACO.COM