



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/22/05 Operator FOUR STAR / CHEVRON API #30-0 45 30783

Property Name KEYS Well No. 3 Location: Unit ___ Section 32 Township 29 Range 10

Well Status (Shut-In or Producing) Tubing 84 Intermediate NA Casing 119 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

START TEST AT 12:50

PRESSURES:

TIME	BRADENHEAD	INTERMEDIATE	CASING
12:55 5 minutes	0		119
1:00 10 minutes	0		119
1:05 15 minutes	0		119
20 minutes			
25 minutes			
30 minutes			

BRADENHEAD FLOWED

INTERMEDIATE FLOWED

Steady Flow _____
Surges _____
Down to Nothing 9 SEC
Nothing _____
Gas _____
Gas & Water _____
Water _____


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

1:10 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BRADEN HEAD BLEED THROUGH 1/4" HOLE



By MIKE DREYER
MAINTENANCE PLANNER
(Position)

Witness NONE - DARYL IS NO LONGER AT EMNRD. TOLD TO GO ON AND TEST

E-mail address MLDR@CHEVRON.COM