

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: San Juan 27-5 Unit 117	Facility Type: Gas Well

Surface Owner Public	Mineral Owner Fee	API No. 3003920221
-----------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 27N	Range 05W	Feet from the 800	North/South Line North	Feet from the 800	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------------

Latitude **36.56369** Longitude **-107.33879**

NATURE OF RELEASE



Type of Release Condensate & Produced Water	Volume of Release 45BBLs	Volume Recovered 45BBLs
Source of Release Below Grade Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 01/28/15 @ 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith, NMOCD	RECEIVED FEB 09 2015 NMOCD DISTRICT III
By Whom? Lisa Hunter	Date and Hour 01/29/15 @ 10:25 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	

If a Watercourse was Impacted, Describe Fully.*
n/a

Describe Cause of Problem and Remedial Action Taken.*
Tank was actively leaking into cribbing when discovered. Water truck as called and recovered fluid. Hole was plugged with Plug n Dike to hold remaining fluid in tank. All equipment was shut down and locked out. No fluid left cribbing area and liner did a good job of retaining the fluid.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 3/13/15	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: February 2, 2015 Phone: (505) 326-9786		

* Attach Additional Sheets If Necessary

#NCS 150 72491 76

①