



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-16-15 Operator Burlington Co API #30-0 45-33633
Property Name Fairmount Corn Well No. 1E Location: Unit 36 Township 31 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 544 Intermediate 1/4 Casing 551 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		551		
10 min	0		551		
15 min	0		551		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

RECEIVED

MAR 16 2015

NMOCD
DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/4

REMARKS:

Nothing when opened. Well shut in - bad pt.
bottom valve needs replaced. ~~Bottom valve needs replaced.~~
fix bottom valve - needs to open all the way

By

(Position)

Witness

E-mail address