



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 07 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-7-15 Operator XTO Energy API #30-0 45-34317
Property Name Kutz Falls SWD Well No. 1 Location: Unit F Section 6 Township 27 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 1646 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min	<u>0</u>		<u>0</u>		
25 min	<u>0</u>		<u>0</u>		
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water <u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/4

REMARKS:

Nothing when opened. at 5 min water
nothing in pipe

By Frank Lutton
XTO SWD FOREMAN
(Position)

Witness

Monica Kuchling
Retest in 30 days

E-mail address