

OIL CONS. DIV DIST. 3

MAY 21 2015

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-22-15 Operator Thompson Engr. & Prod. API # 30-045-27613
Property Name Angel Peak Well No. 11K#2 Location: Unit K Section 11 Township 27N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 1 Intermediate - Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		4		
10 min	0		4		
15 min	0		4		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE -REMARKS: Slight blow when opening ~~bradenhead~~ bradenhead. No pressure after opening.By [Signature]
(Position)

Witness _____