



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

3-0

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/21/2015 Operator COPC API #30-045-34794
Property Name Horton Com B Well No. 101 S Location: Unit A Section 33 Township 31 Range 11
Well Status (Shut In or Producing) Initial PSI: Tubing 42 Intermediate - Casing 57 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	-	57		
10 min	0	-	57		
15 min	0	-	57		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Nothing on bradenhead

By [Signature]
MSO
(Position)

Witness Paul Wade

E-mail address _____

OIL CONS. DIV DIST. 3

MAY 21 2015