



MAILING ADDRESS: PO BOX 3483
FARMINGTON, NM 87499
SHIPPING ADDRESS: 3600 BLOOMFIELD HWY
FARMINGTON, NM 87401
OFFICE: (505) 325-1125
FAX: (505) 326-4803

10/21/05

30-045-32681

To Whom It May Concern:

Phoenix Services ran deviation surveys for the Quinn 336S well located in San Juan County, NM. These deviation surveys are true and accurate based on our daily reports. All of the discs were left with the pumper.


Yours truly,

Rony Simmons

State of New Mexico
County of SAN JUAN
On this 21 day of October 2005, Rony E. Simmons
personally appeared before me,
who is personally known to me,
☒ whose identity I verified on the basis of NM DL

to be the signer of the foregoing document, and he/she acknowledged that
he/she signed it.

My Commission Expires: 11-4-8



Phoenix
Services, LLC

DAILY REPORT

P.O. Box 3483
Farmington, NM 87499-3483

Office (505) 325-1125
Pager (505) 564-5453

Date: SEPT 11, 2005

No. 6279WD
File No. 628
Unit No. 5

Company Name: KOCH EXPLORATION
Well Name: QUINN 336S
County, State: SAN JUAN, NM

Information from company file:

Tbg. Size:
Total Depth:
Perfs:

Foreman: DALTON KING
Pumper:
AFE or DP#:

Casing Psi:
Tubing Psi:
Gauge Ring:
Total Depth: 580'
Fluid Level:
Tight Spots:
Equipment Set @:
PISTON #
BHBS #:

Description of work performed:

RAN DEVIATION TOOL TO 580'-PULLED UP TO 565'-SHOT-SHOWED 1 DEGREE-
RELEASED FROM LOCATION



Phoenix
Services, LLC

DAILY REPORT

P.O. Box 3483
Farmington, NM 87499-3483

Office (505) 325-1125
Pager (505) 564-5453

Date: SEPT 14, 2005

No. 6295WD
File No. 630
Unit No. 1

Company Name: KOCH
Well Name: QUINN 336S
County, State: SAN JUAN, NM

Information from company file:

Tbg. Size:
Total Depth:
Perfs:

Foreman: DALTON KING
Pumper:
AFE or DP#:

Casing Psi:
Tubing Psi:
Gauge Ring:
Total Depth: 1816'
Fluid Level:
Tight Spots:
Equipment Set @:
Piston Serial #:
Bumper Spring Serial #:

Description of work performed:

ON STANDBY WAITING FOR RIG CREW TO ARRIVE ON LOCATION-RAN DEVIATION
TOOL TO 1120'-SHOT-SHOWED 4 DEGREES-RAN DEVIATION TOOL TO 1620'-SHOT
SHOWED 4 DEGREES- RAN DEVIATION TOOL TO 1816'-PULLED UP TO 1800'-SHOT
SHOWED 1 DEGREE-PUMPER DID NOT WANT TO RERUN ANY OF THE SURVEY'S
RELEASED FROM LOCATION



Phoenix Services, LLC

DAILY REPORT

P.O. Box 3483
Farmington, NM 87499-3483

Office (505) 325-1125
Pager (505) 564-5453

Date: SEPT 19, 2005

No. 6348WD
File No. 635
Unit No. 9

Company Name: KOCH
Well Name: QUINN 336S
County, State: SAN JUAN, NM

Information from company file:

Tbg. Size:
Total Depth:
Perfs:

Foreman: MIKE CONFER
Pumper:
AFE or DP#:

Casing Psi:
Tubing Psi:
Gauge Ring:
Total Depth: 2960'
Fluid Level:
Tight Spots:
Equipment Set @:
Piston Serial #:
Bumper Spring Serial #:

Description of work performed:

ON STANDBY WAITING FOR RIG CREW FINISH-RAN DEVIATION TOOL TO 2960'-TD-
PULLED UP TO 2945'-SHOT-SHOWED 7 DEGREES-DRILLING FOREMAN DID NOT WANT
TO RERUN SURVEY AT THAT DEPTH-RELEASED FROM LOCATION

Tool Bent
Re worked for run
9-20-05



Phoenix

Services, LLC

DAILY REPORT

P.O. Box 3483
Farmington, NM 87499-3483

Office (505) 325-1125
Pager (505) 564-5453

Date: Sept 20, 2005

No. 6349WD
File No. 635
Unit No. 5

Company Name: KOCH EXPLORATION
Well Name: QUINN 336S
County, State: SAN JUAN, NM

Information from company file:

Tbg. Size:
Total Depth:
Perfs:

Foreman: DALTON KING
Pumper:
AFE or DP#:

Casing Psi:
Tubing Psi:
Gauge Ring:
Total Depth: 2962'
Fluid Level:
Tight Spots:
Equipment Set @:
Piston Serial #:
Bumper Spring Serial #:

Description of work performed:

RAN DEVIATION TOOL TO 2962'-PULLED UP TO 2950'-SHOT-SHOWED 2 DEGREES-RAN DEVIATION TOOL TO 2600'-SHOT-SHOWED .75 DEGREES- RAN DEVIATION TOOL TO 2300'-SHOT-SHOWED .50 DEGREES- RAN DEVIATION TOOL TO 1800'-SHOT-SHOWED .75 DEGREES- RAN DEVIATION TOOL TO 1620'-SHOT-SHOWED 1 DEGREE- RAN DEVIATION TOOL TO 1120'-SHOT-SHOWED 1 DEGREE-RELEASED FROM LOCATION

