



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

MAY 26 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-26-15 Operator Burlington API #30-0 45-30840
Property Name Dump Mesa Feed Well No. 1M Location: Unit Section 15 Township 30 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 144 Intermediate 0 Casing 145 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	145	0	147
10 min	0	0	146	0	147
15 min	0	0	146	0	147
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH- Puff when opened.
Int light blow when opened. Dead at 31 seconds.

By Don Shampers

Witness Mona Keckling

(Position)

E-mail address