



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 28 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/28/2015 Operator COPC API #30-0 45-10049

Property Name FJ TiH Well No. 2 Location: Unit M Section 35 Township 31 Range 11

Well Status (~~Shut~~ In or Producing) Initial PSI: Tubing ⁵⁷ 57 Intermediate — Casing 71 Bradenhead 11.7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>77</u>		
10 min	<u>0</u>	<u>—</u>	<u>78</u>		
15 min	<u>0</u>	<u>—</u>	<u>80</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Bradenhead blew down to nothing before gas sample could be caught.

By Fred Garcia
Lead Operations
(Position)

Witness Paul Wike

E-mail address —