



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

4.05
9.41
OIL CONS. DIV DIST. 3

MAY 28 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/28/2015 Operator COPC API #30-0 45-35073

Property Name Lester Well No. 1B Location: Unit D Section 3 Township 30 Range 11

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 103 Intermediate 0 Casing 104 Bradenhead 95

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	107	0	109
10 min	0	0	108	0	109
15 min	0	0	109	0	109
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 42 INTERMEDIATE 0

REMARKS:

Bradenhead blew down while getting gas sample. Just a whisper
on intermediate. Gas samples from bradenhead and casing

By Fred Garcia
Lead operations
(Position)

Witness Paul Wicks

E-mail address _____

36.847910000
-107.982790