



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

MAY 28 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/28/2015 Operator COPC API #30-0 45-35081

Property Name Sloane Com Well No. 1F Location: Unit M Section 34 Township 31 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 213 Intermediate 13 Casing 211 Bradenhead 11.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	13	211	0	212
10 min	0	13	212	0	212
15 min	0	13	212	0	213
20 min				0	213
25 min				0	213
30 min				0	213

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing	✓	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead blew down in 2 seconds. Intermediate blew down
to fumes in 2 min. 43 sec. fumes for remainder of 30 min. (5 min. shut in at)
Gas samples from bradenhead, intermediate, and casing.

By Fred Garcia
Lead Operations
(Position)

Witness Paul Wulke

36.848/8422790
-107.98275025

E-mail address _____