



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 08 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-8-15 Operator Burlington Res API #30-0 45-29937
Property Name Montoya A34 Well No. 100 Location: Unit 44 Section 34 Township 32 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 44 Intermediate 4A Casing 62 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		62		
10 min	0		62		
15 min	0		63		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	/
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 4A

REMARKS:

Nothing when opened.

By Lawrence Gallegos

Witness Monica Truchley

(Position)

E-mail address _____