



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

JUN 09 2015

(submit 1 copy to above address)

Date of Test 6/9/2015 Operator Chevron API #30-0 45-3/590

Property Name Mead 27 Well No. 2 Location: Unit F Section 22 Township 32 Range 13

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 40 Intermediate — Casing 5/ Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>57.6</u>		
10 min	<u>0</u>	<u>—</u>	<u>58.7</u>		
15 min	<u>0</u>	<u>—</u>	<u>61.3</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Just a puff on bradenhead through 1/2" pipe sitting

By Lucinda Padella

Witness Paul Wier

(Position)

E-mail address —