

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

JUN 1 0 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test	6-10-15	Operato	Robert L Bayles SAPI #30-045-09630
Property Name	11 1		Location: UnitSection_8 Township_30 Range_12
Well Status(Shut-In or Producing) Initial PSI: Tubing 15 Intermediate A Casing 320 Bradenhead 9			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg			FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min	370		Steady Flow
10 min 0	320		Surges
15 min 0	370		Down to Nothing
20 min			Nothing
25 min			Gas
30 min			Gas & Water
,			Water
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE			
REMARKS: Stacked flowing water at 7 min flowed (Sallon			
in 15 Min. Sample-laken			
By Brandy Armes / Vouca Culling			
Pumper (Position)			
E mail address			