



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-1-14 Operator Devon Energy API #30-0 39-24236
Property Name Sims Mesa SW Well No. 1 Location: Unit 10 Section 10 Township 30 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 1550 Intermediate 1117 Casing -7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>-7</u>		
10 min	<u>0</u>		<u>-7</u>		
15 min	<u>0</u>		<u>-7</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>DIST. 9</u>
Surges	
Down to Nothing	<u>OIL CONS. DIV.</u>
Nothing	
Gas	<u>RCVD JUL 1 14</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1117

REMARKS: this well has liners no intermediate
BH long puff when opened
10 3/4-3616 7 5/8-1117 5 1/2-8956

By Dil Jari
lease operator Tech
(Position)

Witness Mouca Kuchling

E-mail address _____