



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUN 22 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DJS INC

MAY 26 2015

Date of Test 5-14-15 Operator DJ Symons API #30-0 46-33792

Property Name Kimble Wash Well No. 13-1 Location: Unit P Section 13 Township 9N Range 23N

Well Status (Shut-In or Producing) Initial PSI: Tubing 36 Intermediate / Casing 37 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>36</u>		
10 min	<u>0</u>		<u>35</u>		
15 min	<u>0</u>		<u>35</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Oil well with pumping unit

By Cody Hannah

Witness Paul Wicks

Lense Operator
(Position)

E-mail address _____