



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District 3/district.htm](http://emrmd.state.nm.us/ocd/District%203/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUL 02 2015

Date of Test 6-19-15 Operator M3 G Drilling API #30-045-06341

Property Name Marren Well No. 46 Location: Unit K Section 23 Township 27N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 5 Intermediate 0 Casing 3 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>3</u>	<u>0</u>	<u>3</u>
10 min	<u>0</u>	<u>0</u>	<u>3</u>	<u>0</u>	<u>3</u>
15 min	<u>0</u>	<u>0</u>	<u>3</u>	<u>0</u>	<u>3</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

(venerable)

By Terry Hinson
Pumper
(Position)

Witness _____

E-mail address _____