



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrld.state.nm.us/ocd/District III/3district.htm](http://emrld.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 2-2015 Operator SG Interests I, Ltd. API #30-0 45-24160

Property Name SE Cha Cha Unit Well No. 37 Location: Unit 0 Section 15 Township 28N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 45 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
JUL 01 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Blew through 1/2 valve to read
in 1 minute.

By Bruce Wapal
Well Tender
(Position)

Witness Monica Keddling

E-mail address brckinney67@yahoo.com