



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUL 07 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-JUL-2015 Operator X TO API # 30-045-09214

Property Name Stedje Gas Well No. 1 Location: Unit Section 27 Township 30 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing 136 Intermediate N/A Casing 138 Bradenhead 160

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min			141		
10 min			142		
15 min			144		
20 min			145		
25 min			147		
30 min			149		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>X</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u>X</u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 70

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT HAD A STRONG
FLOW FOR 10 SECONDS AND HAD A CONTINUOUS LIGHT
FLOW FOR THE REMAINDER OF THE TEST. REQUESTED A GAS ANALYSIS.

By Ken Durham

Witness John Durham

Production Foreman
(Position)

E-mail address