



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUL 28 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-28-15 Operator Burlington API #30-0 45-34424
Property Name Angel Peak B Well No. 27E Location: Unit 1 Section 25 Township 28 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 61 Intermediate 109 Casing 82 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0	109	83	0	83	Steady Flow	Steady Flow
10 min	0	109	83	0	67	Surges	Surges
15 min	0	109	83	0	57	Down to Nothing	Down to Nothing
20 min				0	54	Nothing	Nothing
25 min				0	52	Gas	Gas
30 min				0	58	Gas & Water	Gas & Water
						Water	Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH dead at 6 seconds - long puff
When opened after 5 min shut in
Int tank start 11.5" - flowing water immediately

By

Braed Parker

Witness

Mona Kuller

(Position)

E-mail address

Attempt to get water sample
11.5" at end of test. 11.5" at end of test.
Gas with water for 4 seconds.
to drop to fumes. 22 seconds.
Plunge camera at 6 min - plunging
at 9 min - casing dropped well
is producing plunging gas 15-20
stopped at 25 min - fumes
test.