



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUL 31 2015

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 31-JULY-2015 Operator BURLING TOV API #30-0 45-05916

Property Name HUECOFARITO Well No. 92 Location: Unit L Section 12 Township 26 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 118 Intermediate N/A Casing 155 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min			155		
10 min			156		
15 min			156		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME OUT.

By Chadwick Randelman

Witness John Durham

(Position)

Email address