

## **NEW MEXICO ENERGY, MINERALS** AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170

http://www.emnrd.state.nm.us/ocd/

OIL CONS. DIV DIST. 3

JUL 3 1 2015

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test	06/2	06/22/15		Four	Four Star Oil Gas			3004528912	
Property Nam	e	SHIOTANI 007			Location: Unit K Section 33			Range 12	
Pressure (Sh			e and Number)  Tubing	1 Interme	diate <u>0</u>	Casing	3 Bradenh	ead <u>0</u>	
OPEN	I BRADENHI	EAD AND	INTERMEDIAT	E TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
Time	, ,		Intermediate	Interme	Casing		Bradenhead Flowed	Intermediate Flowed	
5 minutes	0	Monitor 3	Monitor	Blowdown	Monitor	Steady Flow			
10 minutes	0	2				Surges			
15 minutes	0	2				Down to Nothing			
20 minutes						No Flow	X		
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI	0					Water			
If bradenhead flowed water, check all of the descriptions that apply below:         Clear       Fresh       Salty       Sulfur       Black								_	
REMARKS:									
Ву	Lucinda Padilla			Witness					