



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-AUG-2015 Operator BURLINGTON API #30-0 45-2/156
Property Name RIDDLE G Well No. 3 Location: Unit Section 17 Township 28 Range 8
Well Status(Shut-In or Producing) Initial PSI: Tubing 88 Intermediate N/A Casing 88 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min			88			Steady Flow <u>X</u>	
10 min			88			Surges <u> </u>	
15 min			89			Down to Nothing <u> </u>	
20 min			89			Nothing <u> </u>	
25 min			89			Gas <u> </u>	
30 min			89			Gas & Water <u> </u>	
						Water <u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 13 INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT FLOWED
12G GALLONS OF WATER IN 30 MINUTES REQUESTED A WATER ANALYSIS

By

Chet Rolfe
M50

(Position)

Witness

Jabbar

E-mail address