



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 19 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-19-15 Operator Burlington Res API #30-0 45-05963

Property Name Huachuquito 44 Well No. 91 Location: Unit 12 Section 26 Township 26 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1/4 Casing 62 Bradenhead 62

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>62</u>		
10 min	<u>0</u>		<u>62</u>		
15 min	<u>0</u>		<u>63</u>		
20 min	<u>0</u>		<u>63</u>		
25 min	<u>0</u>		<u>63</u>		
30 min	<u>0</u>		<u>62</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow ✓

Surges

Down to Nothing

Nothing

Gas ✓

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 9

INTERMEDIATE 1/4

REMARKS:

Hard blow 1.5 min to lighter at 1.57 to 1.62
blow - 5 min - 10 - 15 - 20 - 25 - 30 - BH rising slowly
after 5 min. Leak on gate valve for prod. Casing needs
fixed.

By Chorina L. Randleman

Witness

Monica Kuehling
request BH & prod. Casing
gas analysis

(Position)

E-mail address Chorina.L.randleman@conocophillips.com

Well bore & casing