



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-20-15 Operator Burlington Res API #30-0 45-06150

Property Name Bookhaver Corp Well No. 5 Location: Unit 36 Township 27 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 31 Intermediate 0 Casing 38 ^{Sample} Bradenhead 38

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	18	0	31	0	31
10 min	18	0	31	0	31
15 min	18	0	31	0	31
20 min	18	0	31		
25 min	18	0	31		
30 min	18	0	31		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water <u>✓</u>	

OIL CONS. DIV DIST. 3
AUG 20 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY ✓ SULFUR ✓ BLACK ✓

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 37

INTERMEDIATE 0

REMARKS:

Coil-tubing in hole - Casing & tubing the same
6'8 x 24 .5" in at start 14" Int-Nothing when opened.
used to water livestock 2.7 barrels fresh clean water

By Sean Shew

Witness Monica Kuchling

MSO
(Position)

need water analysis

E-mail address _____