



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-20-15 Operator ConocoPhillips API #30-0 45-20443
Property Name Nation WW Field Well No. 7 Location: Unit 6 Section 72 Township 27 Range 8
Well Status(Shut-In or Producing) Initial PSI: Tubing 123 Intermediate N/A Casing 43 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>8</u>		<u>43</u>		
10 min	<u>7</u>		<u>43</u>		
15 min	<u>6</u>		<u>43</u>		
20 min	<u>6</u>		<u>43</u>		
<u>24</u> 25 min	<u>6</u>		<u>43</u>		
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water <u>✓</u>	

OIL CONS. DIV DIST. 3
AUG 20 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 11

INTERMEDIATE N/A

REMARKS:

Steady flow Clear water when opened. through
24 minute test. pit not big enough for 30 minute
test. 19" in 24" container 11.02 back in 24 min.

By Shawn Shaw

Witness

Nomica Fuchina
August water analysis

MSO
(Position)

E-mail address _____