

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

AUG 24 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources Oil & Gas Company	Contact	Lindsay Dumas
Address	3401 East 30 th St, Farmington, NM	Telephone No.	(505) 258-1643
Facility Name	San Juan 29-7 126	Facility Type	Gas

Surface Owner	BLM	Mineral Owner	SF-079514	API No.	30-039-23774
---------------	-----	---------------	-----------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	18	29N	07W	860'	FSL	1025'	FWL	Rio Arriba

Latitude 36.72129 Longitude -107.61491

NATURE OF RELEASE

Type of Release	Hydrocarbon and produced water	Volume of Release	15 bbls HC/ 7 bbls PW	Volume Recovered	0 bbls
Source of Release	Production tank drain line	Date and Hour of Occurrence	unknown	Date and Hour of Discovery	8/17/2015 @ 3:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Cory Smith and Shari Ketcham		
By Whom?	Lindsay Dumas	Date and Hour	8/18/2015 @ 7 AM phone call/ 7:30 AM Email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A vandal opened the drain valve and moved the drain line from dumping into the pit to dumping on the ground; releasing 22 total bbls of hydrocarbon and produced water onto the ground.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 8/2/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/21/2015	Phone: (505) 258-1643	

* Attach Additional Sheets If Necessary

#NCS 15 24 540 401