



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 8-10-2015 Operator Western Minerals & Oil API # 45-23128

Property Name Marron Well No. 5A Location: Unit P Section 27 Township 27N Range 8W

Well Status (Shut-In or Producing) Tubing 15 Intermediate --- Casing 47 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>---</u>	<u>47</u>	Steady Flow	
10 minutes	<u>0</u>	<u>---</u>	<u>47</u>	Surges	
15 minutes	<u>0</u>	<u>---</u>	<u>46</u>	Down to Nothing	
20 minutes	<u>0</u>	<u>---</u>	<u>47</u>	Nothing <u>X</u>	
25 minutes	<u>0</u>	<u>---</u>	<u>46</u>	Gas	
30 minutes	<u>0</u>	<u>---</u>	<u>47</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR --- FRESH --- SALTY --- SULFUR --- BLACK ---

OIL CONS. DIV DIST. 3

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE ---

SEP 03 2015

REMARKS:

No Pressure

By Bob Cherault  
Pumper  
(Position)

Witness Steven Gallegos

E-mail address bob@ccinm.com