



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-10-2015 Operator Western Minerals & Oil API # 45-23128

Property Name Marron Well No. 5A Location: Unit P Section 27 Township 27N Range 8W

Well Status(Shut-In or Producing) Initial PSI: Tubing 15 Intermediate -- Casing 47 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM		
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>47</u>		
10 min	<u>0</u>	<u>—</u>	<u>47</u>		
15 min	<u>0</u>	<u>—</u>	<u>46</u>		
20 min	<u>0</u>	<u>—</u>	<u>47</u>		
25 min	<u>0</u>	<u>—</u>	<u>46</u>		
30 min	<u>0</u>	<u>—</u>	<u>47</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

No Pressure

By Bob Chenault Witness Steven Gallegos

Pumper
(Position)

E-mail address Bob@ccinm.com